

The one way bearing is a new way to play the spin top, brings to you the power of the bearing spinning mixed with the fixed tip regeneration.

To insert the bearing you must remove the tip unscrewing it, after insert a screwdriver into the bearing bore and move gently up and down until the bearing comes out, now remove the spacer you find between the two bearings.



To insert the one way bearing (OWB) put the small washer into the tip, insert the OWB with the rotation writing of the bearing turned to the tip side for right hand players or inverted for left hand players. Gently insert the bearing inside the spacer zone of the Strummo8 spintop (every model can fit it), push the tip until the tip is full insert. Now take out the tip, remove the washer and insert the two ballbearings. Insert the bearing adapter in the internal bearing and screw the tip (if you don't have the adapter screw the nut top-down. Screw until the tip can have a little movement with the body.



Strummo8 di Maurizio Petruccioli